











Front Right Rear




Front Right Rear












Librarian Plymouth Public Library



Architect BF Architects



Chair Community Preservation Committee






Artist retreat?





Bird-watching sanctuary?




Shelter for unhoused?









Three fishing shanties




Two run down




One burnt down




Disassemble buildings




Rebuild on wood piles




Charred wood cladding




Re-use clapboards




Re-use chimney bricks for patio




New observation tower




Connect with platform




Shelter with roof




Collect rainwater






Move in




50 Year Flood Risk: 1% chance

8ft. above sea level


Foundation: treated wood piles




Structure: open web trusses osb sheathing




Air + Vapor Control: osb sheathing




Air + Vapor Control: service chase



Thermal Control: wood fiber insulation




Thermal Control: wood fiber insulation blown cellulose



Thermal Simulation: temperature


0°F 68°F




*generated with THERM 7.8

Water Control: cedar rainscreen parrafin wax coating epdm roof


Interior Finishes: installed over furring strips



Interior Furniture: bamboo plywood low voc materials




Exterior: wood deck




Visual Comfort: even daylighting







Visual Comfort: insulated cellular shades





Visual Comfort: dimmable electric lighting 90+ color rendering index



Thermal Comfort: motorized awning










Thermal Comfort: awning windows


passive ventilation





*based on Grasshopper OpenFoam plugin for Rhino



















Section Detail: dining room / art studio





Dining Room / Art Studio Interior




Kitchen elevation






View from street Flooded street

Floor Plan: first floor





Floor Plan: second floor (







Sophia's watchtower












heat pump water heater



heat pump water heater (ducted)




energy recovery ventilator



washing machine ventless dryer

Mechanical Closet + Bathroom elevation view







Backyard view from river

Typical Singe Family House Construction cost: \$300 / ft²


Nest Zero House Construction cost: \$250 / ft²






^{*} Cost estimate based on RSMeans data

Embodied Carbon & Stored Carbon



Operational Carbon



Massachusetts Stretch Code:

HERS max score:

55 – January 1, 2023

45 – July 1, 2024


Nest Zero:

HERS score:

32 – without PV


0 – with 320 ft² PV

-18 - with 500 ft² PV



^{*} HERS score based on REMRate report

Future Scalability: Lease-to-Own Houses



Future Scalability: Lease-to-Own Houses





Thank You!







