

FUNNEL
HOUSE



U.S. DEPARTMENT
OF ENERGY

SOLAR
DECATHLON



TEAM: INDOAMÉRICA

STUDENT TEAM LEADER



Jheanpiere Sánchez
Architecture

STUDENTS TEAM



Christian Darquea
Architecture



Javier Maigua
Architecture



Wendy Moya
Architecture



Fernando Pazmiño
Architecture

FACULTY LEADER



Arq. Sebastián Alvarado
Architecture



Daniel Poaño
Architecture



Viviana Sinailin
Architecture



Claudia Toledo
Architecture



Rodrigo Erazo
Industrial Ingeniering



FACULTY ADVISORS

FACULTY LEADER

- Arq. Sebastián Alvarado

ARCHITECTURE

- Arq. Teresa Pascual
- Arq. Daniela Ortiz
- Arq. José Leyva

INDUSTRIAL INGENEERING

- Ing. Wilson Chancusig
- Ing. Pablo Ron
- Ing. Paúl Remache

LANGUAGE CENTER

- MSc. Roilys Suarez
- MSc. Lorena Espinosa
- MSc. Samary Guillén
- MSc. Rocío Patiño

BUSINESS MANAGEMENT

- Ing. Alcívar Pila

PARTNERSHIPS



*INSTITUTO DE INVESTIGACIÓN
GEOLÓGICO Y ENERGÉTICO*



CONTENT



LOCATION



DESIGN
PROCESS



USER



FINANCIAL
ANALYSIS



CONSTRUCTION
COST



ARCHITECTURE



INTERIOR
DESIGN



COMFORT



ENERGY PLUS
HOUSE



RESILIENCE



ENGINEERING
SYSTEMS



MECHANICAL
DESIGN



ELECTRIC
DESIGN



PLUMBING
DESIGN



HOME
AUTOMATION



MAINTENANCE



BUILDING
CIRCULARITY



CONCLUSIONS





LOCATION

to activate Windows
Go to Settings to activate Windows



● ECUADOR

● ECUADOR



AMAZON REGION


● NAPO

● NAPO



● TENA

● TENA



● FUNNEL HOUSE

● FUNNEL HOUSE

Tena City





COST-TARGET MARKET

Activar Windows
Ver la Comunicación por Activar Windows.

TENA CANTON: 7 PARISHES



POPULATION CHARACTERISTICS TENA CANTON

- INHABITANTS: 60.880
- POPULATION DENSITY: 234 hab / sq mi
- SURFACE: 1507 sq mi



TENA CITY AND NAPO RIVER



POPULATION SETTLEMENT

SCATTERED



HOUSING TYPOLOFY

OWN HOUSING



ECONOMIC DEVELOPMENT

AGRICULTURE






POTENTIAL CLIENT

Young population between 15 and 35 years of age, with medium-high economic potential.



KICHWA FAMILIES


Residence is patrilocal: the wife moves to live in the house of the parents of the husband and is considered part of that family.






HOUSING

57% Owned house market potential




NUMBER OF PEOPLE PER HOUSE

53% 3-4 inhabitants market potential




AVERAGE HOUSING IN PANO




House Price - 1200 sq ft
\$36 000 - \$48 000







COST-BENEFIT



FUNNEL HOUSE \$62.811 / \$37,2 PER SQ FEET






DESIGN PROCESS

Activar Windows
Ve a Configuración para activar Windows.

ENVIRONMENTAL CONDITIONS



Maximum temperature:
89,60°F
Minimum temperature:
57,20°F



Humidity: 81%-92%



Maximum precipitation:
38553.1 mm




Months with high cloudiness:
February and July.




Months with the most hours of sunshine per day: tropical:
July and August.


“ The building needs to be cooled down, and the relative humidity needs be lowered ”








- ① Elongated form:
Minimize solar exposure
Maximize South ventilation




- ② Open-social spaces:
Natural ventilation
-
- Closed-private spaces:
Improved comfort




- ③ Modularity=Progressive growth






- 4 23,4° wall inclination to avoid the Sun



- 5 Unify, separate and ventilate hot spots

- Dining room
- Kitchen - Bathroom - cellars.
- Bedrooms.



- 6 The building is raised from the ground, to:
- Allow air circulation under it.



The image features a close-up view of maple leaves in silhouette against a soft, hazy sky during sunset or sunrise. The leaves are dark and detailed, with some showing a slight reddish-brown tint. The background is a gradient of light blue and pink. A teal banner with the word 'ARCHITECTURE' in white, bold, sans-serif font is positioned at the bottom left. A white vertical line is on the left side of the banner.

ARCHITECTURE


Settlers Residence




Vernacular Residence



► Vernacular Housing



► Funnel House



“Ekent”

Private Space

“Tankamash”

Social Space

- 1.- Living room, dinning room
- 2.- Kitchen
- 3.- Bathroom
- 4.- Cellars, ducts
- 5.- Bedrooms
- 6.- Hammock room





Bedrooms

Kitchen- Bath room

Leaving Room

Social Spaces

Activar Windows
Ve a Configuración para activar Windows.







OSB Or Oriented Fiber Boards



Bamboo



Ecological stucco of cal



Narrow Slatted toasted bamboo board -VT

MATERIALITY IN INTERIOR DESIGN



The image features a close-up view of maple leaves in silhouette against a soft, hazy sky during sunset or sunrise. The leaves are dark and detailed, with some showing a slight reddish-brown tint. The background is a gradient of light blue and pink. A teal-colored banner is positioned at the bottom left, containing the word 'CONFORT' in white, bold, uppercase letters. A thin white vertical line is located to the left of the banner.


CONFORT



Air quality



water



Thermal comfort



Physical health



Acoustic comfort




food nourishment



Community



Materials




illumination




Innovation




[1 of 215] [May 31, 2020 - 08:00]




[1 of 33] [December 21, 2010 - 08:00]



[1 of 33] [December 21, 2010 - 08:00]




[1 of 33] [June 21, 2010 - 08:00]




Natural Light Analysis


Natural Light
Best Orientation
Best Radiation



NATURAL VENTILATION



NATURAL VENTILATION - MECHANICAL VENTILATION



A close-up photograph of vibrant green evergreen branches, likely a spruce or fir, filling the frame. The branches are densely packed with small, needle-like leaves. The lighting is bright, creating a soft glow and highlighting the texture of the foliage. A dark, rectangular area is visible in the bottom right corner of the image.

ENERGY PLUS HOUSE



Latitude 0°
High solar irradiation



FV energy production House's energy consumption Excess returned to grid
5807 kWh/year - **4338 kWh/year** = **1469 kWh/year**




Fuel Breakdown - TENA- ECUADOR, FUNNEL HOUSE

1 Jan - 31 Dec, Run period

EnergyPlus Output

Evaluation



Room Electricity (kWh)	1225,89
Lighting (kWh)	741,43
DHW (Electricity) (kWh)	1673,76




EnergyPlus Output

Comfort - TENA- ECUADOR, FUNNEL HOUSE


1 Jan - 31 Dec, Run period

Evaluation





Air Temperature (°C)	24,51
Radiant Temperature (°C)	26,26
Operative Temperature (°C)	25,39
Outside Dry-Bulb Temperature (°C)	23,11
Relative Humidity (%)	67,04
Discomfort hrs (all clothing) (hrs)	2783,07





Daylight



Afternoon Light




Lighting Analysis

Interior Light Natural Light


Housing area	lux min	lux recom.	lux optimal
Living Room	200	300	500
Kitchen	100	150	200
Bedroom	100	150	200
Studying room	300	500	750
Circulation	50	100	150
Bedroom	100	150	200



Lighting Analysis



VIDEO DAYLIGHT




VIDEO AFTERNOONLIGHT



An aerial photograph of a river winding through a lush, green forest. The river is the central focus, with its brownish water contrasting against the vibrant green of the trees. The forest is dense and appears to be a tropical or subtropical environment. The lighting is bright, suggesting a sunny day.

RESILIENCE

Activar Windows.
Ve a Configuración para activar Windows.



Earthquake



Structure



Isolation



Recreational Spaces
+
Local food production
+
Internet Connection







Floods




Raise a terre




Land Sliding




Soil Improvement





Insects



AntiBug Layer



Deforestation



Certified Wood






STRUCTURE




Exo - Structure

Concrete Foundation
Bamboo Structure


Wall System




Floor System



Roof System



Window System



BAMBOO -GUADUA ANGUSTIFOLIA



Lifetime	Stem Height	Diameter Radius	Compressive strength	Compression elasticity module	Felxural modulus
50 years	91.86 ft	0.49 ft	37.76	14.35 Gpa	12.16 Gpa




An aerial photograph showing the intricate wooden framework of a large, modern building under construction. The structure is composed of numerous interconnected wooden beams forming a complex, multi-level geometric shape. The building is situated in a dense, lush green forest with tall trees and a well-maintained lawn. The lighting is bright, suggesting a sunny day, and the overall scene conveys a sense of natural integration and architectural precision.

ENGINEERING SYSTEMS

Activar Windows
Ve a Configuración para activar Windows

- OUTSIDE FRESH AIR INLET
- INTAKE DUCT
- EXTRACTION DUCT
- EXHAUST VENTILATION OUTLET



IDEO2
HIGH FLOW BACKFLOW
HEAT RECOVERY


DRIVE PLENUM

EXTRACTION PLENUM



BARJ / BARP SELF-REGULATING
EXTRACTION NOZZLE

PVC OR RECTANGULAR PLASTIC
DUCTS.







- BST THERMOSIPHON




— COLD WATER
— HOT WATER









VAPOR




THERMAL



ACOUSTICS





WATER



AIR





LOCAL MATERIAL, LABOR AND RESEARCH



Stuco



OSB panels



Vapor resistant foam



Certified wood

ESPE University

Universidad de las Fuerzas
Armadas de Ecuador

Palm fiber insulation
research





PALM FIBER

Natural fiber used as insulation for temperature, research by ESPE University

FIBER	Density (g/m ³)	(W/K.m)
Glass Wool	0.011	0.045
NATURAL FIBER		
Palm Fiber	0.078	0.032






SMART BUILDING

Magnetic
Contac Device



Motion
sensor

Camera



Smart
Thermostat

Control





Intelligent
plug





integrates with all devices

SAAS (Software as a service)





MAINTENANCE

LOCAL MATERIALS
Facilitate maintenance




SMART BUILDING
Automated monitoring



MAINTENANCE



TREATED BAMBOO



Palm oil
Water proofing

+

Zinc or Titanium
UV protection

+

Wax finish
Dust protection



WATER RESISTANT STUCCO



3mm (0,1 inch) layer

Maintenance every 2 years

40 years lifetime



ROOF PROTECTION



Protective Paint

- Reflects radiation
- Improves thermal and acoustic insulation
- Moisture control



Service ladder



Gutter net



MATERIALS	USE	LIFETIME	MAINTENANCE TIME
BAMBOO	STRUCTURE	50 YEARS	EVERY 2 YEARS
PANLES OSB	WALLS - FLOORS	40 YEARS	EVERY 2 YEARS
SANWICH TYPE METALLIC PANEL	ROOF	25 YEARS	EVERY 2 YEARS





LIFE CYCLE ASSESSMENT

Building Circularity

① **Material Recovered** 202.2 %

Virgin	0 %
Renewable	67.8 %
Recycled	67.2 %
Reused	67.2 %

② **Material Returned** 100 %

Reuse as material	94.5 %
Recycling	5.5 %
Downcycling ½*	0 %
Use as energy ½*	0 %
Disposal	0 %

151 %



Renew / Reuse / Process for new material




EMBODIED CARBON BENCHMARK

Cradle to grave (A1-A4, B4-B5, C1-C4)	kg CO ₂ e/m ²
< 140 A	211
(140-270) B	
(270-400) C	
(400-530) D	
(530-660) E	
(660-790) F	
> 790 G	

One Click LCA

EMBODIED CARBON BY LIFE-CYCLE STAGE



EMBODIED CARBON BY STRUCTURE - A1-A3

